

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20170815 – E326576  
**Report Reference** E326576 – 20081210  
**Issue Date** 2017-AUGUST-15

**Issued to:** EUCHNER GMBH + CO KG  
Kohlhammerstrasse 16  
Leinfelden  
70771 Echterdingen, GERMANY

**This is to certify that**  
representative samples of

Emergency Stop Devices  
(See Addendum)

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**

ANSI/UL 508, "Industrial Control Equipment."

**Additional Information:**

See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE


**Certificate Number** 20170815 – E326576  
**Report Reference** E326576 – 20081210  
**Issue Date** 2017-AUGUST-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## Addendum –

### Emergency stop pushbuttons:

ES-XW1E-BV412MFR, ES-XW1E-LV412Q4MFR, ES-XW1E-BV401MFR, ES-XW1E-BV411MFR, ES-XW1E-BV413MFR, ES-XW1E-BV402MFR, ES-XW1E-BV422MFR, ES-XW1E-BV403MFR, ES-XW1E-BV404MFR, ES-XW1E-LV401Q4MFR, ES-XW1E-LV411Q4MFR, ES-XW1E-LV413Q4MFR, ES-XW1E-LV402Q4MFR, ES-XW1E-LV422Q4MFR, ES-XW1E-LV403Q4MFR, ES-XW1E-LV404Q4MFR, ES-XW1E-TV412Q4MFR, ES-XW1E-TV403Q4MFR, ES-XN4E-BL412MFRH, ES-XN4E-LL412Q4MFR, ES-XN4E-BL401MFRH, ES-XN4E-BL411MFRH, ES-XN4E-BL413MFRH, ES-XN4E-BL402MFRH, ES-XN4E-BL422MFRH, ES-XN4E-BL403MFRH, ES-XN4E-BL404MFRH, ES-XN4E-LL401Q4MFR, ES-XN4E-LL411Q4MFR, ES-XN4E-LL413Q4MFR, ES-XN4E-LL402Q4MFR, ES-XN4E-LL422Q4MFR, ES-XN4E-LL403Q4MFR, ES-XN4E-LL404Q4MFR, ES-XN4E-T L412Q4MFR, ES-XN4E-T L402Q4MFR, ES-XN4E-T L403Q4MFR



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

